
QC/QA Asphalt Mix Acceptance Procedures



- 1. Observe QC sampling and testing procedures, frequencies, etc.
- 2. Monitors QC control chars of control parameters Individual and Moving Average Results).
- 3. Obtains and tests minimum of 15% of QC split sample frequency (Compares with limits of precision).
- 4. Directs additional QC samples at any time.
- 5. Conducts verification sampling and testing at minimum of 10% of QC frequency.
- 6. Any combination of the above.

